

**TAURUS '92-'95
SHO MODEL**
REPLACEMENT FOR
**331-1546PTU-VC
CORNER LAMP
10PRS 3.92CFT**
**OEM PARTS
331-1546R/L-US**

**TUNING PARTS
331-1546PTU-VC**

**TAURUS '92-'95
LX,SE MODEL**
REPLACEMENT FOR
**331-1516PTU-VC
CORNER LAMP
20PRS 3.61CFT**
**OEM PARTS
331-1516R/L-US**

**TUNING PARTS
331-1516PTU-VC**

TAURUS '96-'97
REPLACEMENT FOR
**331-1403PTU-VC
SIDE LAMP
50PRS 1.63CFT**
**OEM PARTS
331-1403R/L-US**

**TUNING PARTS
331-1403PTU-VC**


MC SABLE '96-'99

THUNDERBIRD '89-'95
REPLACEMENT FOR
**331-1552PTU-VC
CORNER LAMP
20PRS 7.37CFT**
**OEM PARTS
331-1552R/L-US**

**TUNING PARTS
331-1552PTU-VC**


COUGAR '89-'95

**331-1553P-U-C
CORNER LAMP
20PRS 4.84CFT**
**OEM PARTS
331-1553R/L-US**

**TUNING PARTS
331-1553P-U-C**


COUGAR '96-'99