

## SOLARA '99-'01

**REPLACEMENT FOR**
**312-1544PXA-VC  
CORNER LAMP  
20PRS 6.50CFT**
**OEM PARTS  
312-1544R/L-AS**

**TUNING PARTS  
312-1544PXA-VC**


## SUPRA '93

**REPLACEMENT FOR**
**212-1413PTB-VC  
SIDE LAMP  
50PRS 1.49CFT**
**OEM PARTS  
212-1413N-Y**


**TUNING PARTS  
212-1413PTB-VC**


## SUPRA '94-'99

**REPLACEMENT FOR**
**312-1415PXA-VC  
SIDE LAMP  
50PRS 2.48CFT**
**OEM PARTS  
312-1415R/L**

**TUNING PARTS  
312-1415PXA-VC**

**WY5W**
**212-1677PTB-VC  
FRONT LAMP  
20PRS 3.39CFT**
**OEM PARTS  
212-1677R/L-US**

**TUNING PARTS  
212-1677PTB-VC**


'97-'98

## TACOMA 2WD '95-'98

**REPLACEMENT FOR**
**312-1517PTB-1C  
CORNER LAMP  
20PRS 3.57CFT**
**OEM PARTS  
312-1517R/L-AS1**

**TUNING PARTS  
312-1517PTB-1C**

**12V5W**

2WD '95-'96

**TOYOTA**

Toutes les pièces énumérées dans ce catalogue ne sont pas originaux. Alle die in diesem Katalog abgebildeten Artikel, sind nicht original Teile. All items shown in this catalogue are not original parts. Todos los productos de este catalogo no son originales. Tutti i particolari raffigurati in questo catalogo non sono originali.

**307**